

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2374	(hub and raceway and wheel and bearing)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/06 09:26
L2	2131	(hub near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 09:49
L3	20	1 and 2	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 09:29
L4	16	3 and flange	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:51
L5	12	4 and (cpu process\$4 computer memory storage micropeorcess\$4)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:52
L6	2	("6619102").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/02/06 09:45
L7	2	("6471407").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/02/06 09:45
L8	14	1 and (flange near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:54
L9	104	(curved base) near3 (flange near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:50
L12	2	9 and hub	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:52

EAST Search History

L14	17	9 and bearing	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:42
L15	6	14 and wheel	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:45
L16	0	14 and vheicle	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:45
L17	2	14 and vehicle	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:47
L18	236	wheel near7 raceway.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:50
L19	92	18 and (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:58
L20	45	19 and flange.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:51
L21	33	20 and (cpu process\$4 computer memory storage micropeorcess\$4)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:52
L22	29	21 and hub	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:52
L23	7	22 and ((load force stress strain deformation compression tension) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:57
L24	3	22 and (strain near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:57

EAST Search History

L25	6	18 and (strain near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 10:59
-----	---	--	---------------------------------	----	----	------------------

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L25	6	18 and (strain near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/02/06 11:34
L30	125	(73/862.392).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/02/06 13:02
L31	4	30 and 1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/06 13:02